

EXTRACT THE TOOL & SOFTWARE FROM RAR TO FOLDER


NOTE : Software Upgrade tool for Windows XP and Windows 8

Step 01 : Download the WIN RAR file from website

Can download from this link also - <http://www.filehippo.com/search?q=rar>


Note :- If you already have WIN RAR software, then no need to download again

Step 02 : Right click on RAR file (sent by we transfer) & choose to Extract the files..




EXTRACT THE TOOL & SOFTWARE FROM RAR TO FOLDER

Step 03 : Inside the folder have a file as below , pl. extract this also



Step 04 : Extract the software from RAR file



INSTALL THE -- > TOOL DRIVER IN YOUR PC

Step 05 : Open the Following folder

“S56_Tool”

→ “SA”

→ “Driver_Auto_Installer_EXE_v5.1453.03”

Go in **WIN_8** or **WIN7_WINXP** folder (according to your PC configuration)

& Install the driver.  DriverInstall

Step 06 : Open the Following folder

“S56_Tool”

→ “S56_Tool ”

→ “Driver_Auto_Installer_EXE_v1.1236.00”


→ “Driver_Auto_Installer_EXE_v1.1236.00”

→ “SmartPhoneDriver “

→Driver_Auto_Installer_v1.1236.00”

→Go in **X64** or **X86** folder (according to your PC configuration)

→Install the driver  spinstall

→Install the driver  dpinst

INSTALL THE -- > TOOL DRIVER IN YOUR PC


Step 07 : Open the Following folder

“S56_Tool”


→ “S56_Tool ”

→” SP_Flash_Tool_exe_Windows_v5.1516.00”

→”SP_Flash_Tool_exe_Windows_v5.1516.00” and Find “flash_tool”



Click on “flash_tool”




This window will be open

INSTALL THE -- > PHONE DRIVER IN YOUR PC

Step 08 : Make the phone “Factory Reset” & Make it ON

Step 09 : Connect the Phone with your PC through USB cable

Check Point :- Make sure USB cable shall be of Phone (Not Power Bank)



PC will take the Phone Driver Automatically & after successful install ...message as above picture shall appear


Note

If you already connected this phone before with same PC then it will not show the Driver update process & the above message will not appear

Means -- > Your PC already have the Phone Driver

UPLOAD THE -- > New Software in Phone

Step 10 : Open the folder "SP_Flash_Tool_exe_Windows_v5.1516.00" and Find "flash_tool"




This window
Will open

UPLOAD THE -- > New Software in Phone

Step 11 : Select the software to be Upload

Click here & Navigate to the folder where the file “ZURI_S56_A_Ver_08_2016-6-3” was Extracted And open folder “IMAGE” and Select the file “MT6592_Android_scatter”



Select “Firmware Upgrade”


After select the software -- > It will upload in Tool & Status will show here -- > Wait until complete

UPLOAD THE -- > New Software in Phone


Step 12 : Make the Phone "OFF" -- > Remove the Battery -- > Again Insert the Battery

Check Point :- Only Insert the Battery, But do not make the Phone "ON"


Step 12 : Click Download -- > Press the Vol -ve key of Phone -- > Connect the USB to Phone



After Connect the USB to Phone -- > Software upload to phone will Start -- > & Will Show the Below Progress



After Complete the successful loading of Software -- > Will Show the Download OK



Note: Sometimes this Process does not complete at first attempt. If it Fails , Try few more times

Step 13 : If Software not upload successfully -- > Will Show **Fail**

Pl. Note :- If getting fail -- > Pl. try again from [Step 11](#)

Step 14 : Remove the battery -- > Insert it again and turn the Phone ON.

Pl. Note :- First Boot after new software installation will take time probably about 10minutes.